

Sample Photos for Room Inventory Checklist

Hong Kong Shue Yan University

Hall Management Unit

所屬床位的照片 Photos For the Bed/ Room:



Research Complex
研究院綜合大樓



Residential and Amenities Complex
宿舍文康大樓

不妥當的設施照片 Photos For the Inappropriate Facilities: A) 房門 / 牆壁 / 地板 Door / Walls / Floor

- Damaged wall
牆壁受損



不妥當的設施照片 Photos For the Inappropriate Facilities:

B) 房間 In Rooms

- Broken bookshelf
書架受損
- Damaged wall
牆壁受損



不妥當的設施照片 Photos For the Inappropriate Facilities:

B) 房間 In Rooms

- Damaged bed frame
床架受損



不妥當的設施照片 Photos For the Inappropriate Facilities:

B) 房間 In Rooms

- Damaged Wardrobe
衣櫃受損



不妥當的設施照片 Photos For the Inappropriate Facilities: B) 房間 In Rooms

- Bed with stickers
床貼軟墊

